

## **Hot Work Permit**

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Instructions		Required Precautions Checklist
Supervisor: 1. Complete precaution chec 2. Complete this form and re 3. Issue Part 2 to competent	tain Part 1	<ul> <li>Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED</li> <li>Hot Work equipment is in good working order</li> </ul>
hot work         Permit Information         Hot work done by:       Image: Content of the colspan="2">Content of the colspan="2"         Location/ building and floor:       Multi-Disciplinary (MDS)         Sth       Sth         Reason for job:       Soldering		Requirements within 35 ft. of hot work         Flammable liquid, dust, link and oily deposits removed and floor swept clean         Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe)         Nearby activities evaluated for conditions that could be affected by hot work         Path of likely sparks evaluated         Combustible floors wet down, covered with damp sand or fire-resistive sheets         Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields         All wall and floor openings covered
		<ul> <li>All wall and hool openings covered</li> <li>Fire resistive covers and metal shields provided as needed</li> </ul>
Personal Protective Equipment (if applicable)         □       Welder's hood with appropriate lenses         □       Welder's gloves		<ul> <li>Protect or shut down ducts and conveyors that might carry sparks to distant combustible material</li> </ul>
<ul> <li>Leather jacket/clothing</li> <li>Head Protection</li> <li>Hearing Protection</li> <li>Respirator Type/cartridge:</li> </ul>		<ul> <li>Hot work on walls, ceilings or roofs</li> <li>Construction is noncombustible and without combustible covering or insulation</li> <li>Combustible material on other side of walls, ceilings or roofs is moved away</li> </ul>
Other:		Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer           Name:         Dwayne Deaton           Signature:         Duck Signature:		<ul> <li>Enclosed equipment cleaned of all combustible material</li> <li>Containers purged of flammable liquid/vapor</li> <li>Pressurized vessels, piping and equipment removed from service, isolated and vented</li> </ul>
I verify the above information has been examined, the precautions checked on the Required Precautions Checklist have been taken to prevent fire, and		Hot work inside of enclosed spaces (i.e., inside of tanks) <ul> <li>Adequate ventilation provided</li> </ul>
permission is authorized for this work.		Atmosphere checked with gas detector per confined space permit
Hot Work Approval           Name:         Drew Parks		Area purged of any flammable or toxic vapors
Signature:		<ul> <li>Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work</li> </ul>
Date:		Hot work/Fire Safety Notifications
Emergency 8593214701 Contact # :		Location of nearest fire alarm known
Permit Dates		$\Box$ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated Date: 04/25/2024	Time: 07:45	precautions area below)
Permit Expires Date: 04/25/2024	Time: 15:45	Escape routes maintained and known by personnel Fire Watch/Hot work area monitoring
Date and time Date: work completed	Time:	<ul> <li>Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased</li> <li>Fire watch is provided with suitable extinguishers</li> </ul>
Final Fire Watch Date: Check-up	Time:	□ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below) Signature:		Special Instructions When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review