Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	IIISLI UCLIOIIS		nequireu Frecautions Checkiist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
 Complete precaution checklist at right 			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
Complete this form and retain Part 1			
Issue Part 2 to competent person performing			☐ Hot Work equipment is in good working order
hot work			Requirements within 35 ft. of hot work
Permit Information			☐ Flammable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by:			
☐ UK Employee	☑ Contra	ctor	☐ Explosive atmosphere in area eliminated (hot work is not to be conducted in a
Location/ building Chemistry-Physics Building			classified area unless made safe)
			☐ Nearby activities evaluated for conditions that could be affected by hot work
and floor:			☐ Path of likely sparks evaluated
	4		☐ Combustible floors wet down, covered with damp sand or fire-
Dooson for job.	Malalia a		resistive sheets
Reason for job:	Welding		☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
			☐ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			
☐ Welder's hood with appropriate lenses			Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's gloves			combustible material
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
			insulation
☐ Hearing Protection			
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
☐ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: Will Gentry			☐ Containers purged of flammable liquid/vapor
Will Gently			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
			Venteu
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			
Checklist have been taken to prevent fire, and			☐ Adequate ventilation provided
permission is authorized for this work.			☐ Atmosphere checked with gas detector per confined space permit
Hot Work Approval			The mosphere encoured with gas detector per commed space permit
Name: James A Beazley			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights,
			live electrical work
Date:			Liet week / Fine Cofety Netifications
			Hot work/Fire Safety Notifications
Emergency 8593965635			☐ Location of nearest fire alarm known
Contact # :			
Downsit Astrontal	Permit Dates	T:	☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date:	Time:	precautions area below)
	12/13/2022	07:00	☐ Escape routes maintained and known by personnel
Permit Expires	Date:	Time:	Escape Toutes maintained and known by personner
	12/13/2022	15:00	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up	Date:	Time.	The watch trained in use of equipment and in sounding didin.
,		1	Special Instructions
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review