

## **Hot Work Permit**

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

|--|

	Instructions		Required Precautions Checklist
<ol> <li>Supervisor:</li> <li>Complete precaution checklist at right</li> <li>Complete this form and retain Part 1</li> <li>Issue Part 2 to competent person performing</li> </ol>			<ul> <li>Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED</li> <li>Hot Work equipment is in good working order</li> </ul>
hot work Hot work done by: UK Employee Location/ building and floor: Reason for job:	Permit Information by: ee I Contractor ing Center for Robotics & Manufacturing Systems Basemeny		Requirements within 35 ft. of hot work         □       Flammable liquid, dust, link and oily deposits removed and floor swept clean         □       Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe)         □       Nearby activities evaluated for conditions that could be affected by hot work         □       Path of likely sparks evaluated         □       Combustible floors wet down, covered with damp sand or fire-resistive sheets         □       Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields         □       All wall and floor openings covered
Demonstration of Devot		((6,	□ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)         □       Welder's hood with appropriate lenses         □       Welder's gloves			Protect or shut down ducts and conveyors that might carry sparks to distant combustible material
<ul> <li>Leather jacket/clothing</li> <li>Head Protection</li> <li>Hearing Protection</li> <li>Respirator Type/cartridge:</li> </ul>			<ul> <li>Hot work on walls, ceilings or roofs</li> <li>Construction is noncombustible and without combustible covering or insulation</li> <li>Combustible material on other side of walls, ceilings or roofs is moved away</li> </ul>
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
ŀ	lot Work Performe	r	□ Enclosed equipment cleaned of all combustible material
Name: John Anderson		n	<ul> <li>Containers purged of flammable liquid/vapor</li> </ul>
Signature:			<ul> <li>Pressurized vessels, piping and equipment removed from service, isolated and vented</li> </ul>
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions Checklist have been taken to prevent fire, and permission is authorized for this work.			<ul> <li>Adequate ventilation provided</li> <li>Atmosphere checked with gas detector per confined space permit</li> </ul>
Hot Work Approval			
Name: Brian Hardin			Area purged of any flammable or toxic vapors
Signature:			<ul> <li>Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work</li> </ul>
Date:			Hot work/Fire Safety Notifications
Emergency 8596213951 Contact # :			Location of nearest fire alarm known
Demoit Arti i i	Permit Dates	Timer	□ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 04/06/2023	Time: 06:52	precautions area below)
Permit Expires	Date: 04/06/2023	Time: 14:52	<ul> <li>Escape routes maintained and known by personnel</li> <li>Fire Watch/Hot work area monitoring</li> </ul>
Date and time	Date:	Time:	□ Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased
work completed			Fire watch is provided with suitable extinguishers
Final Fire Watch Check-up	Date:	Time:	□ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)			Special Instructions When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review
	· · · · · · · · · · · · · · · · · · ·		