

## **Hot Work Permit**

## BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Instructions			Required Precautions Checklist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
Complete precaution checklist at right     Complete this form and ration Part 1			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
<ol> <li>Complete this form and retain Part 1</li> <li>Issue Part 2 to competent person performing</li> </ol>			☐ Hot Work equipment is in good working order
hot work			Dequirements within 25 ft of het work
Permit Information			Requirements within 35 ft. of hot work  ☐ Flammable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by:			Explosive atmosphere in area eliminated (hot work is not to be conducted in a
☐ UK Employee ☐ Contractor			classified area unless made safe)
Location/ building	Center for Robotics	s & Manufacturing	☐ Nearby activities evaluated for conditions that could be affected by hot work
and floor:	Systems		☐ Path of likely sparks evaluated
	Basement		☐ Combustible floors wet down, covered with damp sand or fire-
Daggar fau iah	NA/ - Lal'		resistive sheets
Reason for job:	Welding		☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Personal Protective Equipment (if applicable)			☐ Fire resistive covers and metal shields provided as needed
☐ Welder's hood with appropriate lenses			☐ Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's gloves			combustible material
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: Jonathan Jones			☐ Containers purged of flammable liquid/vapor
			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			
Checklist have been taken to prevent fire, and			☐ Adequate ventilation provided
permission is authorized for this work.			☐ Atmosphere checked with gas detector per confined space permit
Hot Work Approval			Area nurred of any flammable or tayin yaners
Name: Brian Hardin			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 8596213951			☐ Location of nearest fire alarm known
Contact # :			
Permit Activated	Permit Dates  Date:	Time:	If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	05/10/2023	07:00	precautions area below)
Permit Expires	+		☐ Escape routes maintained and known by personnel
Permit Expires	Date: 05/10/2023	Time: 17:00	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up			
Fire Watch Inspector Signature (below)			Special Instructions  When het work is complete submit completed permit to supervisor or project
Signature:			When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review
oignature.			aa <sub>0</sub> a. 131 ok Erio review