

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	111311 UCTIO113		nequireu Frecautions Checkist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
Complete precaution checklist at right			
Complete this form and retain Part 1			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
Issue Part 2 to competent person performing			☐ Hot Work equipment is in good working order
hot work			Requirements within 35 ft. of hot work
Permit Information			☐ Flammable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by:			
☐ UK Employee	☑ Contra	ctor	☐ Explosive atmosphere in area eliminated (hot work is not to be conducted in a
Location/ building UK Hospital - Chandler Medical			classified area unless made safe)
and floor:	Center & Hospital		☐ Nearby activities evaluated for conditions that could be affected by hot work
and noor:		,	☐ Path of likely sparks evaluated
	ground		☐ Combustible floors wet down, covered with damp sand or fire-
Reason for job:	Soldering		resistive sheets
Reason for job.	Soldering		☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
	L		☐ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			☐ Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's hood with appropriate lenses			combustible material
☐ Welder's gloves			Compustible material
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
l <u> </u>			☐ Combustible material on other side of walls, ceilings or roofs is moved away
Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: Kevin Snyder			☐ Containers purged of flammable liquid/vapor
Cignatura			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			not work inside of enclosed spaces (i.e., inside of talks)
Checklist have been taken to prevent fire, and			☐ Adequate ventilation provided
permission is authorized for this work.			
Hot Work Approval			☐ Atmosphere checked with gas detector per confined space permit
News			☐ Area purged of any flammable or toxic vapors
Name: Matt Abrams		3	Thea purged of any numinable of toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights,
			live electrical work
Date:			Hot work/Fire Safety Notifications
-			Hot work/File safety Notifications
Emergency 859-248-9611			☐ Location of nearest fire alarm known
Contact # : Permit Dates			
Permit Activated	Date:	Time:	If no alarm present, what method will be used to raise the alarm? (List in other
I CITILI ACTIVATED	06/02/2023	13:32	precautions area below)
			☐ Escape routes maintained and known by personnel
Permit Expires	Date:	Time:	
	06/02/2023	17:32	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up			
Fire Watch Inspector Signature (below)			Special Instructions
			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review
İ			