

## **Hot Work Permit**

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

0076	2023
0)	

	Instructions		Required Precautions Checklist
2. Complete	e precaution check e this form and reta t 2 to competent p	ain Part 1	<ul> <li>Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED</li> <li>Hot Work equipment is in good working order</li> </ul>
hot work Hot work done by: UK Employee Location/ building and floor: Reason for job:	Permit Information	actor	Requirements within 35 ft. of hot work         □       Flammable liquid, dust, link and oily deposits removed and floor swept clean         □       Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe)         □       Nearby activities evaluated for conditions that could be affected by hot work         □       Path of likely sparks evaluated         □       Combustible floors wet down, covered with damp sand or fire-resistive sheets         □       Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields         □       All wall and floor openings covered
	<u> </u>	<i></i>	□ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)         □       Welder's hood with appropriate lenses         □       Welder's gloves			Protect or shut down ducts and conveyors that might carry sparks to distant combustible material
<ul> <li>Leather jacket/</li> <li>Head Protectio</li> <li>Hearing Protectio</li> <li>Respirator Ty</li> </ul>	clothing n tion		<ul> <li>Hot work on walls, ceilings or roofs</li> <li>Construction is noncombustible and without combustible covering or insulation</li> <li>Combustible material on other side of walls, ceilings or roofs is moved away</li> </ul>
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
H Name:	<b>lot Work Performe</b> VestFabricati	-	<ul> <li>Enclosed equipment cleaned of all combustible material</li> <li>Containers purged of flammable liquid/vapor</li> </ul>
Signature:			<ul> <li>Pressurized vessels, piping and equipment removed from service, isolated and vented</li> </ul>
I verify the above i precautions checke Checklist have bee permission is autho	ed on the Required n taken to prevent orized for this wor	l Precautions t fire, and k.	Hot work inside of enclosed spaces (i.e., inside of tanks)         Adequate ventilation provided         Atmosphere checked with gas detector per confined space permit
Hot Work Approval Name: Ted MacDonald			Area purged of any flammable or toxic vapors
Signature: Ted MacDonald			<ul> <li>Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work</li> </ul>
Date:			Hot work/Fire Safety Notifications
Emergency 859-629-2020 Contact # :			Location of nearest fire alarm known
	Permit Dates	 1	□ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 06/09/2023	Time: 07:00	precautions area below)
Permit Expires	Date: 06/09/2023	Time: 17:00	<ul> <li>Escape routes maintained and known by personnel</li> <li>Fire Watch/Hot work area monitoring</li> </ul>
Date and time work completed	Date:	Time:	<ul> <li>Fire watch will be provided for a minimum of 30 minutes after work has ceased</li> <li>Fire watch is provided with suitable extinguishers</li> </ul>
Final Fire Watch Check-up	Date:	Time:	□ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)		ire (below)	Special Instructions When hot work is complete, submit completed permit to supervisor or project
Signature:		_ ()	manager for UK EHS review
•			-