

## **Hot Work Permit**

## BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Criecklist
Complete     Issue Part     hot work	precaution checkles this form and retal 2 to competent permit Information  Center for Robotics Systems  Basement  Soldering	in Part 1 erson performing ctor	Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED  Hot Work equipment is in good working order  Requirements within 35 ft. of hot work  Flammable liquid, dust, link and oily deposits removed and floor swept clean  Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe)  Nearby activities evaluated for conditions that could be affected by hot work  Path of likely sparks evaluated  Combustible floors wet down, covered with damp sand or fire-resistive sheets  Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Personal Protective Equipment (if applicable)		if applicable)	☐ Fire resistive covers and metal shields provided as needed
☐ Welder's hood with appropriate lenses			☐ Protect or shut down ducts and conveyors that might carry sparks to distant combustible material
☐ Welder's gloves ☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
			insulation
<u> </u>			☐ Combustible material on other side of walls, ceilings or roofs is moved away
Other:  Hot Work Performer			Hot work on enclosed equipment (i.e., welding on tanks)
			☐ Enclosed equipment cleaned of all combustible material
Name: John Anderson			☐ Containers purged of flammable liquid/vapor
Signature:			☐ Pressurized vessels, piping and equipment removed from service, isolated and vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions Checklist have been taken to prevent fire, and permission is authorized for this work.			<ul> <li>□ Adequate ventilation provided</li> <li>□ Atmosphere checked with gas detector per confined space permit</li> </ul>
Hot Work Approval			Atthosphere checked with gas detector per commed space permit
Name: Brian Hardin			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 8596213951 Contact #:			☐ Location of nearest fire alarm known
Permit Dates		T .	☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 06/09/2023	Time: 07:00	precautions area below)
Permit Expires	Date: 06/09/2023	Time: 15:00	☐ Escape routes maintained and known by personnel
Date and time			Fire Watch/Hot work area monitoring
work completed	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased ☐ Fire watch is provided with suitable extinguishers
Final Fire Watch Check-up	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)			Special Instructions
Signature:			When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review
			•