

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Checklist
2. Complete	 ipervisor: 1. Complete precaution checklist at right 2. Complete this form and retain Part 1 		 Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order
hot work F Hot work done by: UK Employee Location/ building and floor:	Permit Information	ctor	Requirements within 35 ft. of hot work □ Flammable liquid, dust, link and oily deposits removed and floor swept clean □ Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) □ Nearby activities evaluated for conditions that could be affected by hot work □ Path of likely sparks evaluated □ Combustible floors wet down, covered with damp sand or fire-resistive sheets □ Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields
			□ All wall and floor openings covered
Personal Protective Equipment (if applicable) □ Welder's hood with appropriate lenses □ Welder's gloves □ Leather jacket/clothing			 Fire resistive covers and metal shields provided as needed Protect or shut down ducts and conveyors that might carry sparks to distant combustible material Hot work on walls, ceilings or roofs
 Head Protection Hearing Protection Respirator Type/cartridge: 			 Construction is noncombustible and without combustible covering or insulation Combustible material on other side of walls, ceilings or roofs is moved away
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			□ Enclosed equipment cleaned of all combustible material
Name: Ricky Wright Signature:			 Containers purged of flammable liquid/vapor Pressurized vessels, piping and equipment removed from service, isolated and vented
I verify the above information has been examined, the precautions checked on the Required Precautions Checklist have been taken to prevent fire, and permission is authorized for this work.			Hot work inside of enclosed spaces (i.e., inside of tanks) Adequate ventilation provided Atmosphere checked with gas detector per confined space permit
Hot Work Approval			Area purged of any flammable or toxic vapors
Signature: Landon Lowry			 Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 8597498693 Contact # :			Location of nearest fire alarm known
Dormit Activity	rmit Activated Date: Time:		\Box If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 06/26/2023	11:16	precautions area below)
Permit Expires	Date: 06/26/2023	Time:	Escape routes maintained and known by personnel
Date and time	Date:	16:16 Time:	<i>Fire Watch/Hot work area monitoring</i> Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased
work completed	Date.	Time.	Fire watch is provided with suitable extinguishers
Final Fire Watch Check-up	Date:	Time:	□ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)			Special Instructions When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review