Hot Work Permit



BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Supervisor: 1. Complete precaution checklist at right 2. Complete this form and retain Part 1 3. Issue Part 2 to competent person performing hot work Permit Information Hot work done by: UK Employee Location/ building and floor: Chemistry-Physics Building and floor: Reason for job: Soldering Sprinkler protection in service. If fire suppression is taken offline, Location in service. If suppression is taken offline, Location in service. If suppression is taken offline, Location in service is approach to the first and suppression is taken offline.	vept clean ducted in a v hot work
Personal Protective Equipment (if applicable) Fire resistive covers and metal shields provided as needed	nect with
Protect or shut down ducts and conveyors that might carry snarks	o distant
weider's nood with appropriate lenses combustible material	
☐ Welder's gloves	
☐ Leather jacket/clothing Hot work on walls, ceilings or roofs	
☐ Head Protection ☐ Construction is noncombustible and without combustible covering	or
☐ Hearing Protection insulation	_
☐ Respirator Type/cartridge: ☐ Combustible material on other side of walls, ceilings or roofs is mo	red away
Other: Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer	•
Name: John Anderson	
☐ Pressurized vessels, piping and equipment removed from service, i	solated and
Signature: vented	iolatea aria
I verify the above information has been examined, the Hot work inside of enclosed spaces (i.e., inside of tanks	l
precautions checked on the Required Precautions Checklist have been taken to prevent fire, and	
Checkist have been taken to prevent me, and	
permission is authorized for this work. Atmosphere checked with gas detector per confined space permit	
Hot Work Approval Name: Brian Hardin Area purged of any flammable or toxic vapors	
Signature: Other permits completed as required: Lock-out/tag-out, working are live electrical work	heights,
Date: Hot work/Fire Safety Notifications	
Emergency 8596213951	
Permit Dates If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated Date: Time: precautions area below)	בושני וווי טנווכו
07/17/2023 07:00	
Permit Expires Date: Time: Escape routes maintained and known by personnel	
07/17/2023 15:00 Fire Watch/Hot work area monitoring	
Date and time Date: Time: □ Fire watch will be provided for a minimum of 30 minutes after wor	chas ceased
work completed	
Final Fire Watch Date: Time: ☐ Fire watch trained in use of equipment and in sounding alarm. Check-up	
Special Instructions	
Fire Watch Inspector Signature (below) Signature: When hot work is complete, submit completed permit to superviso manager for UK EHS review	or project