

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE ALL PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Instructions			Required Precautions Checklist
Supervisor:			Chrinkler protection in convice of fire suppression is taken effline LIV Fire
	precaution checkl	-	☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED
· ·	this form and reta		☐ Hot Work equipment is in good working order
3. Issue Part 2 to competent person performing			Thot work equipment is in good working order
hot work Permit Information			Requirements within 35 ft. of hot work
Hot work done by:			Flammable liquid, dust, link and oily deposits removed and floor swept clean
☐ UK Employee ☐ Contractor			Explosive atmosphere in area eliminated (hot work is not to be conducted in a
Location/ building UK Hospital - Chandler Medical			classified area unless made safe)
and floor: Center & Hospital (Pavilion H)			☐ Nearby activities evaluated for conditions that could be affected by hot work
	1		☐ Path of likely sparks evaluated
			☐ Combustible floors wet down, covered with damp sand or fire- resistive sheets
Reason for job:	Welding		☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
			☐ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			☐ Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's hood with appropriate lenses			combustible material
☐ Welder's gloves			Hot work on walls, ceilings or roofs
Leather jacket/clothing			☐ Construction is noncombustible and without combustible covering or
☐ Head Protection			insulation
☐ Hearing Protection ☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Namo			☐ Enclosed equipment cleaned of all combustible material
Noah Patrick			☐ Containers purged of flammable liquid/vapor ☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented versels, piping and equipment removed from service, isolated and
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			☐ Adequate ventilation provided
Checklist have been taken to prevent fire, and			Adequate ventilation provided
permission is authorized for this work. Hot Work Approval			☐ Atmosphere checked with gas detector per confined space permit
Name: James A Beazley			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			_
			Hot work/Fire Safety Notifications
Emergency 859-396-5635 Contact #:			☐ Location of nearest fire alarm known
	Permit Dates		☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date:	Time:	precautions area below)
	08/23/2023	07:00	☐ Escape routes maintained and known by personnel
Permit Expires	Date: 08/23/2023	Time: 17:00	
Date and time	Date:	Time:	Fire Watch/Hot work area monitoring ☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed	Dutc.	Time.	☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up			
Fire Watch Inspector Signature (below)			Special Instructions When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review
5.0			
1			