

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE ALL PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	instructions		Required Precautions Checklist
Supervisor: 1. Complete precaution checklist at right 2. Complete this form and retain Part 1 3. Issue Part 2 to competent person performing hot work Permit Information Hot work done by: UK Employee Contractor			Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swept clean Explosive atmosphere in area eliminated (hot work is not to be conducted in a
Ta			classified area unless made safe)
Location/building	Grenan Journalish	і Біаў	☐ Nearby activities evaluated for conditions that could be affected by hot work
and floor:			☐ Path of likely sparks evaluated
	Ground		☐ Combustible floors wet down, covered with damp sand or fire-
Reason for job:	Caldania		resistive sheets
Reason for job.	Soldering		☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Davis and Dust	antina Familiana ant i	lif amuliandala)	☐ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			☐ Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's hood		nses	combustible material
☐ Welder's gloves			
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: John Anderson			☐ Containers purged of flammable liquid/vapor
			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			☐ Adequate ventilation provided
Checklist have been taken to prevent fire, and permission is authorized for this work.			
Hot Work Approval			Atmosphere checked with gas detector per confined space permit
Name: Brian Hardin			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights,
			live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 8596213951 Contact #:			☐ Location of nearest fire alarm known
Permit Dates			☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date:	Time:	precautions area below)
	08/23/2023	10:02	
Permit Expires	Date:	Time:	☐ Escape routes maintained and known by personnel
	08/23/2023	16:02	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch is provided with suitable extinguishers ☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up	Date.	Time.	The watch trained in use of equipment and in sounding diam.
,			Special Instructions
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review
			1