

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Checklist
2. Complete	e precaution checklist at right e this form and retain Part 1 t 2 to competent person performing		 Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order
hot work Permit Information Hot work done by: □ □ UK Employee ☑ Contractor Location/ building and floor: □ Central Heating Plant #2 1 Reason for job: Welding Personal Protective Equipment (if applicable)		ant #2	Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swept clean Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) Nearby activities evaluated for conditions that could be affected by hot work Path of likely sparks evaluated Combustible floors wet down, covered with damp sand or fire-resistive sheets Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields All wall and floor openings covered Fire resistive covers and metal shields provided as needed Protect or shut down ducts and conveyors that might carry sparks to distant
 Welder's hood with appropriate lenses Welder's gloves Leather jacket/clothing Head Protection Hearing Protection Respirator Type/cartridge: 			 Frotect of shart down ducts and conveyors that hight carry sparks to distant combustible material Hot work on walls, ceilings or roofs Construction is noncombustible and without combustible covering or insulation Combustible material on other side of walls, ceilings or roofs is moved away
Other: Hot Work Performer Name: Wes Griebel Signature:			Hot work on enclosed equipment (i.e., welding on tanks) □ Enclosed equipment cleaned of all combustible material □ Containers purged of flammable liquid/vapor □ Pressurized vessels, piping and equipment removed from service, isolated and vented
I verify the above information has been examined, the precautions checked on the Required Precautions Checklist have been taken to prevent fire, and permission is authorized for this work. Hot Work Approval Name:			Hot work inside of enclosed spaces (i.e., inside of tanks) Adequate ventilation provided Atmosphere checked with gas detector per confined space permit Area purged of any flammable or toxic vapors
Name: James A Beazley Signature: Signature:			 Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 859-396-5635 Contact # :			Location of nearest fire alarm known
Permit Activated	Permit Dates Date: 09/07/2023	Time: 07:00	If no alarm present, what method will be used to raise the alarm? (List in other precautions area below)
Permit Expires	Date: 09/07/2023	Time: 15:00	 Escape routes maintained and known by personnel Fire Watch/Hot work area monitoring
Date and time work completed <i>Final Fire Watch</i> <i>Check-up</i>	Date: Date:	Time: Time:	 Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased Fire watch is provided with suitable extinguishers Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below) Signature:			Special Instructions When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review