

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

0193	2023
------	------

	Instructions			Required Precautions Checklist
Supervisor:		ist at sight	Sprin	kler protection in service. If fire suppression is taken offline, UK Fire
	e precaution checkl e this form and reta	-		hal's Office AND UK Delta Room MUST BE NOTIFIED
	t 2 to competent p		🗆 Hot V	Vork equipment is in good working order
hot work			Requirements within 35 ft. of hot work	
	Permit Informatior	1	🗆 Flamı	nable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by: UK Employee	🗹 Contra		•	sive atmosphere in area eliminated (hot work is not to be conducted in a field area unless made safe)
Location/ building	UK Hospital - Cha			by activities evaluated for conditions that could be affected by hot work
and floor:	Center & Hospital	(Pavilion H)		of likely sparks evaluated
	1			oustible floors wet down, covered with damp sand or fire- ive sheets
Reason for job:	Welding		🗆 Remo	we other combustible material where possible. Otherwise, protect with
				oved welding pads, blankets and curtains or metal shields
				all and floor openings covered
Personal Prot	ective Equipment	(if applicable)		esistive covers and metal shields provided as needed
□ Welder's hood	with appropriate le	enses		ct or shut down ducts and conveyors that might carry sparks to distant oustible material
□ Welder's gloves			come	
Leather jacket/	-			Hot work on walls, ceilings or roofs ruction is noncombustible and without combustible covering or
Head Protection		L Const insula		
Hearing Protection Respirator Type/cartridge:		Comb	oustible material on other side of walls, ceilings or roofs is moved away	
□ Other:				Hot work on enclosed equipment (i.e., welding on tanks)
н	lot Work Performe	r	🗆 Enclo	sed equipment cleaned of all combustible material
Name:	Noah Patric	κ	🗆 Conta	iners purged of flammable liquid/vapor
Signature:			Press vente	urized vessels, piping and equipment removed from service, isolated and
I verify the above i	nformation has be	en examined the	vente	Hot work inside of enclosed spaces (i.e., inside of tanks)
I verify the above information has been examined, the precautions checked on the Required Precautions				
Checklist have bee	n taken to prevent	fire, and	🗆 Adeq	uate ventilation provided
permission is authorized for this work.		🗆 Atmo	sphere checked with gas detector per confined space permit	
Hot Work Approval Name: James A Beazley		🗆 Area	purged of any flammable or toxic vapors	
Signature:			r permits completed as required: Lock-out/tag-out, working at heights, lectrical work	
Date:			Hot work/Fire Safety Notifications	
Emergency 859-396-5635 Contact # :		🗆 Locat	ion of nearest fire alarm known	
	Permit Dates	1	□ If no	alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 09/06/2023	Time: 07:00		utions area below)
Permit Expires	Date: 09/06/2023	Time: 15:00	🗆 Escap	e routes maintained and known by personnel
Date and time	Date:	Time:	Eiro y	Fire Watch/Hot work area monitoring
work completed	Date.	Time.		vatch will be provided for a minimum of 30 minutes after work has ceased vatch is provided with suitable extinguishers
Final Fire Watch Check-up	Date:	Time:	🛛 Fire w	atch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)		\\/hen	Special Instructions hot work is complete, submit completed permit to supervisor or project	
Signature:		when	manager for UK EHS review	