

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Checklist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
Complete precaution checklist at right Complete this form and retain Part 1			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
· ·			☐ Hot Work equipment is in good working order
Issue Part 2 to competent person performing hot work			
Permit Information			Requirements within 35 ft. of hot work
Hot work done by:			Flammable liquid, dust, link and oily deposits removed and floor swept clean
☐ UK Employee	☑ Contra	ctor	☐ Explosive atmosphere in area eliminated (hot work is not to be conducted in a
Location/ building Peter P. Bosomworth Health Sciences			classified area unless made safe)
and floor:	Research Bldg	Tarriodan Colonoco	in Nearby activities evaluated for conditions that could be affected by not work
and noor.	Ath/ponthouse		Path of likely sparks evaluated
	4th/penthouse		☐ Combustible floors wet down, covered with damp sand or fire-
Reason for job:	Soldering		resistive sheets
			☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Personal Protective Equipment (if applicable)			Fire resistive covers and metal shields provided as needed
☐ Welder's hood with appropriate lenses			Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's gloves			combustible material
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Namo:			Containers purged of flammable liquid/vapor
John Anderson			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			☐ Adequate ventilation provided
Checklist have been taken to prevent fire, and permission is authorized for this work.			
Hot Work Approval			☐ Atmosphere checked with gas detector per confined space permit
Name: BrianHardin			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights,
oignature.			live electrical work
Date:			
			Hot work/Fire Safety Notifications
Emergency 8596213951			☐ Location of nearest fire alarm known
Contact # : Permit Dates			
Permit Activated	Date:	Time:	If no alarm present, what method will be used to raise the alarm? (List in other precautions area below)
	09/18/2023	07:46	precautions area below)
Permit Expires	Date:	Time:	☐ Escape routes maintained and known by personnel
T CITITE EXPIRES	09/18/2023	14:46	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up	Date.	Tille.	The water trained in use of equipment and in sounding diarm.
,			Special Instructions
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review