

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

0231	2023
31	ũ

Instructions		Required Precautions Checklist	
Supervisor: 1. Complete precaution che 2. Complete this form and r 3. Issue Part 2 to competen	etain Part 1	 Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order 	
hot work		Requirements within 35 ft. of hot work	
Permit Informat Hot work done by: □ UK Employee	tractor	 Flammable liquid, dust, link and oily deposits removed and floor swept clean Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) Nearby activities evaluated for conditions that could be affected by hot work Path of likely sparks evaluated Combustible floors wet down, covered with damp sand or fire-resistive sheets 	
		 Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields All wall and floor openings covered 	
Personal Protective Equipme	nt (if applicable)	□ Fire resistive covers and metal shields provided as needed	
 Welder's hood with appropriate lenses Welder's gloves 		Protect or shut down ducts and conveyors that might carry sparks to distant combustible material	
 Leather jacket/clothing Head Protection Hearing Protection Respirator Type/cartridge:		 Hot work on walls, ceilings or roofs □ Construction is noncombustible and without combustible covering or insulation □ Combustible material on other side of walls, ceilings or roofs is moved away 	
Other:		Hot work on enclosed equipment (i.e., welding on tanks)	
Hot Work Perfor Name: Noah Pai		 Enclosed equipment cleaned of all combustible material Containers purged of flammable liquid/vapor 	
Signature:		 Pressurized vessels, piping and equipment removed from service, isolated and vented 	
I verify the above information has precautions checked on the Requi Checklist have been taken to prev permission is authorized for this w	red Precautions ent fire, and	Hot work inside of enclosed spaces (i.e., inside of tanks) Adequate ventilation provided	
Hot Work Approval		Atmosphere checked with gas detector per confined space permit	
Name: James A Beazley		Area purged of any flammable or toxic vapors	
Signature:		 Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work 	
Date:		Hot work/Fire Safety Notifications	
Emergency 859-396-5635 Contact # :		Location of nearest fire alarm known	
Permit Dates Permit Activated Date:	Time:	If no alarm present, what method will be used to raise the alarm? (List in other	
09/20/2023	07:00	precautions area below)	
Permit Expires Date: 09/20/2023	Time: 17:00	 Escape routes maintained and known by personnel Fire Watch/Hot work area monitoring 	
Date and time Date: work completed	Time:	 Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased Fire watch is provided with suitable extinguishers 	
Final Fire Watch Date: Check-up	Time:	□ Fire watch trained in use of equipment and in sounding alarm.	
Fire Watch Inspector Signature (below)		Special Instructions When hot work is complete, submit completed permit to supervisor or project	
Signature:		manager for UK EHS review	