

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

0241	2023
241)23

	Instructions		Required Precautions Checklist	
2. Complete	precaution checkli this form and reta 2 to competent pe	in Part 1	 Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swept clean Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) Nearby activities evaluated for conditions that could be affected by hot work Path of likely sparks evaluated Combustible floors wet down, covered with damp sand or fire-resistive sheets Remove other combustible material where possible. Otherwise, protect with 	
Hot work done by: UK Employee Location/ building and floor:	Permit Information	dler Medical		
			 approved welding pads, blankets and curtains or metal shields All wall and floor openings covered Fire resistive covers and metal shields provided as needed 	
Personal Protective Equipment (if applicable) □ Welder's hood with appropriate lenses □ Welder's gloves □ Leather jacket/clothing			Protect or shut down ducts and conveyors that might carry sparks to distant combustible material	
Leather jacket/c Head Protectior Hearing Protect Respirator Typ	ion		 Hot work on walls, ceilings or roofs Construction is noncombustible and without combustible covering or insulation Combustible material on other side of walls, ceilings or roofs is moved away 	
Other:	ot Work Performe Kevin Snyder		 Hot work on enclosed equipment (i.e., welding on tanks) Enclosed equipment cleaned of all combustible material Containers purged of flammable liquid/vapor Pressurized vessels, piping and equipment removed from service, isolated and 	
Signature: I verify the above information has been examined, the precautions checked on the Required Precautions Checklist have been taken to prevent fire, and		Precautions fire, and	vented Hot work inside of enclosed spaces (i.e., inside of tanks) Adequate ventilation provided	
permission is autho	orized for this work lot Work Approval	•	Atmosphere checked with gas detector per confined space permit	
Name: Bart Bowman			Area purged of any flammable or toxic vapors	
Signature:			 Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work 	
Date:			Hot work/Fire Safety Notifications	
Emergency 859-248-9611 Contact # :			Location of nearest fire alarm known	
Permit Activated	Permit Dates Date: 09/26/2023	Time: 09:29	□ If no alarm present, what method will be used to raise the alarm? (List in other precautions area below)	
Permit Expires	Date:	Time:	Escape routes maintained and known by personnel	
Date and time work completed	09/26/2023 Date:	17:29 Time:	 Fire Watch/Hot work area monitoring Fire watch will be provided for a minimum of 30 minutes after work has ceased Fire watch is provided with suitable extinguishers 	
Final Fire Watch Check-up	Date:	Time:	 Fire watch trained in use of equipment and in sounding alarm. Special Instructions 	
Fire Watch Inspector Signature (below) Signature:		e (below)	When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review	