

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Checklist	
2. Complete 3. Issue Part hot work Hot work done by: UK Employee Location/ building and floor: Reason for job:	e precaution checkle this form and retate to competent properties to the competent properties the competent properties to the competent properties the co	ain Part 1 erson performing actor Inder Medical (Pavilion H) (if applicable)	Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swept clean Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) Nearby activities evaluated for conditions that could be affected by hot work Path of likely sparks evaluated Combustible floors wet down, covered with damp sand or fire-resistive sheets Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields All wall and floor openings covered Fire resistive covers and metal shields provided as needed Protect or shut down ducts and conveyors that might carry sparks to distant	
☐ Welder's hood with appropriate lenses			combustible material	
☐ Welder's gloves				
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs	
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or	
☐ Hearing Protection			insulation	
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away	
☐ Other:			Hot work on enclosed equipment (i.e., welding on tanks)	
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material	
Nama			☐ Containers purged of flammable liquid/vapor	
Noah Patrick				
Signature:			☐ Pressurized vessels, piping and equipment removed from service, isolated and vented	
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)	
precautions checked on the Required Precautions			☐ Adequate ventilation provided	
Checklist have been taken to prevent fire, and				
permission is authorized for this work.			☐ Atmosphere checked with gas detector per confined space permit	
Hot Work Approval			☐ Area purged of any flammable or toxic vapors	
Name: James A Beazley		ley	- The parged of any naminable of toxic vapors	
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work	
Date:			Hot work/Fire Safety Notifications	
Emergency 859-396-5635 Contact #:			☐ Location of nearest fire alarm known	
Permit Dates			☐ If no alarm present, what method will be used to raise the alarm? (List in other	
Permit Activated	Date:	Time:	 If no alarm present, what method will be used to raise the alarm? (List in other precautions area below) 	
- Similar totaled	10/17/2023	07:00	precautions area below;	
Dormit Evniros		+	Escape routes maintained and known by personnel	
Permit Expires	Date: 10/17/2023	Time: 17:00	Fire Watch/Hot work area monitoring	
Date and time	Date:	Time:		
work completed	Date.	Tillie.	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased	
			☐ Fire watch is provided with suitable extinguishers	
Final Fire Watch Check-up	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm. Special Instructions	
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project	
Signature:			manager for UK EHS review	
L				