

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

| 0295 | 2023 |
|------|------|
| j. | 23 |

| | Instructions | | Required Precautions Checklist | |
|--|---|--------------------------------|---|--|
| 2. Complete | precaution checkli this form and reta 2 to competent pe | in Part 1 | Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order | |
| hot work F Hot work done by: UK Employee Location/ building and floor: Reason for job: | Permit Information | ctor rth Health Sciences | Requirements within 35 ft. of hot work □ Flammable liquid, dust, link and oily deposits removed and floor swept clean □ Explosive atmosphere in area eliminated (hot work is not to be conducted in a classified area unless made safe) □ Nearby activities evaluated for conditions that could be affected by hot work □ Path of likely sparks evaluated □ Combustible floors wet down, covered with damp sand or fire-resistive sheets □ Remove other combustible material where possible. Otherwise, protect with approved welding pads, blankets and curtains or metal shields □ All wall and floor openings covered □ Fire resistive covers and metal shields provided as needed □ Protect or shut down ducts and conveyors that might carry sparks to distant | |
| Welder's hood v Welder's gloves Leather jacket/c Head Protection Hearing Protect Respirator Typ | clothing | | Frotect of shat down docts and conveyors that might carry sparks to distant combustible material Hot work on walls, ceilings or roofs Construction is noncombustible and without combustible covering or insulation Combustible material on other side of walls, ceilings or roofs is moved away | |
| Other: Hot Work Performer | | | Hot work on enclosed equipment (i.e., welding on tanks) | |
| Name: Signature: | Rob Mohr | | Enclosed equipment cleaned of all combustible material Containers purged of flammable liquid/vapor Pressurized vessels, piping and equipment removed from service, isolated and vented | |
| I verify the above in precautions checke Checklist have been permission is autho | d on the Required n taken to prevent | Precautions fire, and c. | Hot work inside of enclosed spaces (i.e., inside of tanks) Adequate ventilation provided Atmosphere checked with gas detector per confined space permit | |
| Name: Brian Hardin | | | Area purged of any flammable or toxic vapors | |
| Signature: | | | Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work | |
| Date: | | | Hot work/Fire Safety Notifications | |
| Emergency 8596213951 Contact # : | | | Location of nearest fire alarm known | |
| Permit Activated | Permit Dates Date: 10/31/2023 | Time: 06:59 | If no alarm present, what method will be used to raise the alarm? (List in other precautions area below) | |
| Permit Expires | Date: 10/31/2023 | Time: 14:59 | Escape routes maintained and known by personnel Fire Watch/Hot work area monitoring | |
| Date and time work completed | Date: | Time: | Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased Fire watch is provided with suitable extinguishers | |
| Final Fire Watch Check-up | Date: | Time: | □ Fire watch trained in use of equipment and in sounding alarm. | |
| Fire Watch Signature: | Inspector Signatu | re (below) | Special Instructions When hot work is complete, submit completed permit to supervisor or project manager for UK EHS review | |