

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

0313	2023
\sim	

	Instructions		Required Precautions Checklist
Supervisor:			
	Complete precaution checklist at right		Sprinkler protection in service. If fire suppression is taken offline, UK Fire Marshal's Office AND UK Delta Room MUST BE NOTIFIED
	e this form and reta t 2 to competent po		Hot Work equipment is in good working order
hot work		erson performing	
	Permit Information		Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by:			 Explosive atmosphere in area eliminated (hot work is not to be conducted in a
UK Employee 🖸 Contractor			classified area unless made safe)
Location/ building and floor: UK Hospital - Chandler Medical Center & Hospital (Pavilion H)			Nearby activities evaluated for conditions that could be affected by hot work
and floor:			Path of likely sparks evaluated
	Ground		Combustible floors wet down, covered with damp sand or fire-
Reason for job:	Welding		resistive sheets
	Ū		Remove other combustible material where possible. Otherwise, protect with approved welding pade blackets and subtring or matel shields
			approved welding pads, blankets and curtains or metal shields All wall and floor openings covered
			 Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			 Protect or shut down ducts and conveyors that might carry sparks to distant
□ Welder's hood with appropriate lenses		enses	combustible material
U Welder's gloves			Hot work on walls, ceilings or roofs
 Leather jacket/ Head Protection 	-		 Construction is noncombustible and without combustible covering or
Head Protection Hearing Protection			insulation
□ Respirator Type/cartridge:			□ Combustible material on other side of walls, ceilings or roofs is moved away
□ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Н	lot Work Performe	r	Enclosed equipment cleaned of all combustible material
Name:	Noah Patrick	(Containers purged of flammable liquid/vapor
Signature:			□ Pressurized vessels, piping and equipment removed from service, isolated and
Signature.			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			Adequate ventilation provided
Checklist have been taken to prevent fire, and permission is authorized for this work.			
Hot Work Approval			Atmosphere checked with gas detector per confined space permit
Name: James A Beazley		еу	Area purged of any flammable or toxic vapors
Signature:			Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency 859-396-5635			
Contact # :			Location of nearest fire alarm known
Permit Activated	Permit Dates	Timor	□ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date: 11/09/2023	Time: 07:00	precautions area below)
Permit Expires	Date:	Time:	Escape routes maintained and known by personnel
	11/09/2023	17:00	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	□ Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased
work completed			Fire watch is provided with suitable extinguishers
Final Fire Watch Check-up	Date:	Time:	□ Fire watch trained in use of equipment and in sounding alarm.
Fire Watch Inspector Signature (below)		re (below)	Special Instructions When hot work is complete, submit completed permit to supervisor or project
Signature:		. ,	manager for UK EHS review