

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Supervisor: 1. Complete precaution checklist at right 2. Complete this form and retain Part 1 3. Issue Part 2 to competent person performing hot work Permit Information Hot work done by: UK Employee Location/ building and floor: UK Hospital - Chandler Medical Center & Hospital (Pavilion H) Sprinkler protection in service. If fire suppression is taken offlimation Marshal's Office AND UK Delta Room MUST BE NOTIFIED Hot Work equipment is in good working order Requirements within 35 ft. of hot work Explosive atmosphere in area eliminated (hot work is not to be classified area unless made safe) Nearby activities evaluated for conditions that could be affect Path of likely sparks evaluated	,	
Reason for job: Soldering Remove other combustible material where possible. Otherwis approved welding pads, blankets and curtains or metal shield: All wall and floor openings covered Fire resistive covers and metal shields provided as needed	ted by hot work e- se, protect with	
Personal Protective Equipment (if applicable) Protect or shut down ducts and conveyors that might carry sp	narks to distant	
Welder's hood with appropriate lenses combustible material	Jai KS LU UISLAIIL	
☐ Welder's gloves		
☐ Leather jacket/clothing Hot work on walls, ceilings or roofs	_	
☐ Head Protection ☐ Construction is noncombustible and without combustible covers	ering or	
☐ Hearing Protection insulation		
☐ Respirator Type/cartridge: ☐ Combustible material on other side of walls, ceilings or roofs i	is moved away	
Other: Hot work on enclosed equipment (i.e., welding on	tanks)	
Hot Work Performer	•	
Name: Kevin Snyder		
☐ Pressurized vessels inining and equipment removed from serv	vice, isolated and	
Signature: vented vented		
I verify the above information has been examined, the Hot work inside of enclosed spaces (i.e., inside of the control of the c	tanks)	
I verify the above information has been examined, the precautions checked on the Required Precautions Hot work inside of enclosed spaces (i.e., inside of the control of t	tanksj	
Checklist have been taken to prevent fire, and		
permission is authorized for this work. ☐ Atmosphere checked with gas detector per confined space pe	ormit .	
Hot Work Approval		
Name: Mike Goldey		
Signature: Other permits completed as required: Lock-out/tag-out, work live electrical work	king at heights,	
Date: Hot work/Fire Safety Notifications		
Emergency 859-248-9611		
Permit Dates ☐ If no alarm present, what method will be used to raise the ala	arm? (List in other	
Permit Activated Date: Time: precautions area below) 11/08/2023 07:46		
Permit Expires Date: Time: Escape routes maintained and known by personnel		
11/08/2023 15:46 Fire Watch/Hot work area monitoring		
Date and time Date: Time: ☐ Fire watch will be provided for a minimum of 30 minutes after	r work has ceased	
work completed		
Final Fire Watch Date: Time: Fire watch trained in use of equipment and in sounding alarm.		
Special Instructions		
Fire Watch Inspector Signature (below) Signature: When hot work is complete, submit completed permit to supermite to sup	ervisor or project	