

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

Supervisor: 1. Complete precaution checklist at right 2. Complete this form and retain Part 1 Het Work organization in service. If fire suppression is taken offline, UK Marshal's Office AND UK Delta Room MUST BE NOTIFIED	
3. Issue Part 2 to competent person performing hot work Permit Information Hot work done by: □ UK Employee Location/ building and floor: Reason for job: Welding Hot Work equipment is in good working order Requirements within 35 ft. of hot work Flammable liquid, dust, link and oily deposits removed and floor swe Explosive atmosphere in area eliminated (hot work is not to be conductassified area unless made safe) Nearby activities evaluated for conditions that could be affected by hearby activities evaluated Combustible floors wet down, covered with damp sand or fireresistive sheets Remove other combustible material where possible. Otherwise, protapproved welding pads, blankets and curtains or metal shields	ot clean cted in a ot work
☐ All wall and floor openings covered	
Personal Protective Equipment (if applicable) Fire resistive covers and metal shields provided as needed	
☐ Welder's shood with appropriate lenses ☐ Welder's releves ☐ Welder's releves	distant
☐ Welder's gloves ☐ Leather jacket/clothing Hot work on walls, ceilings or roofs	
to collection	
Theating Protection	l away
The product of the pr	auwuy
Other: Hot work on enclosed equipment (i.e., welding on tanks)	
Hot Work Performer	
Name: Noah Patrick	
Signature: Pressurized vessels, piping and equipment removed from service, iso vented	ated and
I verify the above information has been examined, the Hot work inside of enclosed spaces (i.e., inside of tanks)	
precautions checked on the Required Precautions Checklist have been taken to prevent fire, and	
normission is authorized for this work	
Hot Work Approval Atmosphere checked with gas detector per confined space permit	
Name: James A Beazley Area purged of any flammable or toxic vapors	
Signature: Other permits completed as required: Lock-out/tag-out, working at h live electrical work	eights,
Date: Hot work/Fire Safety Notifications	
Emergency 859-396-5635	
Permit Dates ☐ If no alarm present, what method will be used to raise the alarm? (List	t in other
Permit Activated Date: Time: precautions area below) 11/16/2023 07:01	
Permit Expires Date: Time: □ Escape routes maintained and known by personnel	
11/16/2023 17:01 Fire Watch/Hot work area monitoring	
	as ceased
Date and time Date: Time: ☐ Fire watch will be provided for a minimum of 30 minutes after work I ☐ Fire watch is provided with suitable extinguishers	
work completed ☐ Fire watch is provided with suitable extinguishers ☐ Fire watch trained in use of equipment and in sounding alarm.	
work completed Final Fire Watch Date: Check-up Time: Time: Time: Special Instructions	
work completed ☐ Fire watch is provided with suitable extinguishers Final Fire Watch ☐ Date: ☐ Fire watch trained in use of equipment and in sounding alarm. Check-up	r project