

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	IIIStructions		nequired Frecautions Checkist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
Complete precaution checklist at right			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
2. Complete this form and retain Part 1			
3. Issue Part 2 to competent person performing			☐ Hot Work equipment is in good working order
hot work			Requirements within 35 ft. of hot work
Permit Information			☐ Flammable liquid, dust, link and oily deposits removed and floor swept clean
Hot work done by:			☐ Explosive atmosphere in area eliminated (hot work is not to be conducted in a
☐ UK Employee ☐ Contractor			classified area unless made safe)
Location/building	UK Hospital - Cha		☐ Nearby activities evaluated for conditions that could be affected by hot work
and floor:	Center & Hospital	(Pavilion H)	☐ Path of likely sparks evaluated
	Ground		☐ Combustible floors wet down, covered with damp sand or fire-
			resistive sheets
Reason for job:	Welding		Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Personal Protective Equipment (if applicable)			Fire resistive covers and metal shields provided as needed
☐ Welder's hood with appropriate lenses			Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's gloves			combustible material
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
I			☐ Combustible material on other side of walls, ceilings or roofs is moved away
Respirator Type/cartridge:			
Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: Noah Patrick			☐ Containers purged of flammable liquid/vapor
Signature:			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature.			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			That work morae or endlosed spaces (ne.), morae or tarms,
Checklist have been taken to prevent fire, and			☐ Adequate ventilation provided
permission is authorized for this work.			Atmosphere shocked with gas detector per confined space permit
Hot Work Approval			→ Atmosphere checked with gas detector per confined space permit
Name: James A Beazley			☐ Area purged of any flammable or toxic vapors
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights,
			live electrical work
Date:			Hot work/Fire Safety Notifications
Emergency Contact #:			☐ Location of nearest fire alarm known
Permit Dates			☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date:	Time:	precautions area below)
	03/28/2024	07:00	precautions area below)
Dormit Evniros	Date:	Time:	☐ Escape routes maintained and known by personnel
Permit Expires	03/28/2024	17:00	Eira Match/Hat work area monitoring
Date and time			Fire Watch/Hot work area monitoring
	Date:	Time:	☐ Fire watch will be provided for a minimum of <i>30 minutes</i> after work has ceased
work completed			Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up			Special Instructions
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review