

Hot Work Permit

BEFORE INITIATION HOT WORK, ENSURE <u>ALL</u> PRECAUTIONS ARE IN PLACE! MAKE SURE AN APPROPRIATE FIRE EXTINGUIRSHER IS READILY AVAILABLE!

	Instructions		Required Precautions Checklist
Supervisor:			☐ Sprinkler protection in service. If fire suppression is taken offline, UK Fire
Complete precaution checklist at right Complete this form and retain Part 1			Marshal's Office AND UK Delta Room MUST BE NOTIFIED
 Complete this form and retain Part 1 Issue Part 2 to competent person performing 			☐ Hot Work equipment is in good working order
hot work			
Permit Information			Requirements within 35 ft. of hot work
Hot work done by:			Flammable liquid, dust, link and oily deposits removed and floor swept clean
☐ UK Employee ☐ Contractor			☐ Explosive atmosphere in area eliminated (hot work is not to be conducted in a
I=			classified area unless made safe)
Location/building	rence nan		☐ Nearby activities evaluated for conditions that could be affected by hot work
and floor:			☐ Path of likely sparks evaluated
	All Floors		☐ Combustible floors wet down, covered with damp sand or fire-
Reason for job:	A actulona/avugan	motal autting	resistive sheets
Reason for job.	Acetylene/oxygen	metal cutting	☐ Remove other combustible material where possible. Otherwise, protect with
			approved welding pads, blankets and curtains or metal shields
			☐ All wall and floor openings covered
Dougonal Duct	ostiva Favrinanant i	if amplicable)	☐ Fire resistive covers and metal shields provided as needed
Personal Protective Equipment (if applicable)			☐ Protect or shut down ducts and conveyors that might carry sparks to distant
☐ Welder's hood with appropriate lenses			combustible material
☐ Welder's gloves			
☐ Leather jacket/clothing			Hot work on walls, ceilings or roofs
☐ Head Protection			☐ Construction is noncombustible and without combustible covering or
☐ Hearing Protection			insulation
☐ Respirator Type/cartridge:			☐ Combustible material on other side of walls, ceilings or roofs is moved away
☐ Other:			Hot work on enclosed equipment (i.e., welding on tanks)
Hot Work Performer			☐ Enclosed equipment cleaned of all combustible material
Name: Connor Featherston			☐ Containers purged of flammable liquid/vapor
			☐ Pressurized vessels, piping and equipment removed from service, isolated and
Signature:			vented
I verify the above information has been examined, the			Hot work inside of enclosed spaces (i.e., inside of tanks)
precautions checked on the Required Precautions			☐ Adequate ventilation provided
Checklist have been taken to prevent fire, and			- Adequate ventilation provided
permission is authorized for this work.			☐ Atmosphere checked with gas detector per confined space permit
Name: David Lambert			☐ Area purged of any flammable or toxic vapors
David Lambert			
Signature:			☐ Other permits completed as required: Lock-out/tag-out, working at heights, live electrical work
Date:			
			Hot work/Fire Safety Notifications
Emergency 8596214880 Contact #:			☐ Location of nearest fire alarm known
Permit Dates			☐ If no alarm present, what method will be used to raise the alarm? (List in other
Permit Activated	Date:	Time:	precautions area below)
	04/24/2024	07:31	
Permit Expires	Date:	Time:	☐ Escape routes maintained and known by personnel
	04/24/2024	17:31	Fire Watch/Hot work area monitoring
Date and time	Date:	Time:	☐ Fire watch will be provided for a minimum of 30 minutes after work has ceased
work completed			☐ Fire watch is provided with suitable extinguishers
Final Fire Watch	Date:	Time:	☐ Fire watch trained in use of equipment and in sounding alarm.
Check-up	Date.	Time.	The water trained in use of equipment and in sounding diam.
,			Special Instructions
Fire Watch Inspector Signature (below)			When hot work is complete, submit completed permit to supervisor or project
Signature:			manager for UK EHS review